

Collet chuck, ER16M





Número de pieza 7.074.670

para Hyundai WIA SKT32A

Volumen de suministro without wrench and collets

Accesorios Collets see Equipment for Toolholders Z2.1  
Spanner wrench 10022



Datos Técnicos sujetos a cambios

18.01.2010 | 26.11.2012

ESA Eppinger GmbH | Breitwiesenweg 2-8 | 73770 Denkendorf, Germany | [www.eppinger.de](http://www.eppinger.de)